

VCDS

Windows Based VAG/VAS Emulator Running on Windows 10 x64

Version: Release 17.1.3

www.Ross-Tech.com

Dealer/Shop Name:

Workshop Code: 000 00000

Diagnostic Trouble Code Report

Wednesday, 24, June, 2020, 22:36:08:39744

VIN: WAUZZZ8KX8A000906 License Plate:

Mileage: 110210km-68481mi Repair Order:

Control Module Part Number: 8K0 907 379 K HW: 8K0 907 379 K

Component and/or Version: ESP8 front H03 0180

Software Coding: 030500

Work Shop Code: WSC 06325 000 00000

VCID: 418E9E46D8128A49A6-8014

2 Faults Found:

01314 - Engine Control Module

013 - Check DTC Memory

Freeze Frame:

Fault Status: 01101101

Fault Priority: 6

Fault Frequency: 5

Reset counter: 253

Mileage: 109859 km

Time Indication: 0

Date: 2020.06.19

Time: 20:45:02

Freeze Frame:

Hex Value: 0x0000

Hex Value: 0x40A2

Hex Value: 0x0209

Hex Value: 0x46AA

Hex Value: 0x00FF

00473 - Control Module for Elect. Park/Hand Brake (J540)

013 - Check DTC Memory

Freeze Frame:

Fault Status: 01101101

Fault Priority: 6

Fault Frequency: 5

Reset counter: 253

Mileage: 109859 km

Time Indication: 0

Date: 2020.06.19

Time: 20:45:02